


## BUILDING SAFETY CERTIFICATE

This is certify that the building of BETHEL MISSION SCHOOL ANUPPUR DISTRICT ANUPPUR (M.P.) run by BETHEL MISSION EDUCATIONAL SOCIETY, ANUPPUR, DISTRICT ANUPPUR (M.P.) has been visited and inspected. It has been observed on visual inspection that the existing ground and first floor of the building of the said school seems to be safe under basic circumstances. It is fit in all respect to run the school. ON THE DATE OF INSPECTION i.e. 6/6/21

Further additional work provided. Inward paper structural Design. Approved By EXCEL CIVIL ENGINEER  
This certificate is being for the purpose of affiliation from CBSE.

Duplicate copy  
S  
25/10/21

  
16/121  
Sub Div. District Officer  
W.D. Sub Div. Anuppur (M.P.)